


ROTHCO CLOTHING SIZE CHART



Workwear Coverall

Size	Chest (Inches)	Sleeve (Inches)	Inseam (Inches)	Waist (Inches)
S	21.26	24.41	29.13	18.90
M	22.04	24.80	29.92	19.69
L	22.84	29.92	30.71	20.47
XL	23.62	25.59	31.50	21.26
2XL	24.41	25.98	32.28	22.05
3XL	25.19	26.38	33.07	22.83



How to Measure: Measure from armpit to armpit to find the chest width 1 inch below the armpit seam. For the sleeve length, measure from the shoulder point to the end of the cuff. Measure horizontally from pass-through pocket to pass-through pocket for the waist. The inseam length can be found by measuring from the crotch down the end of the coverall.

Use the chart to find your measurement